



# To our customers who use Evaporative Air Cooler, RKF Series

## Cooling Element (50812-201007)

Symptom: Smelling and/or poor wind  
Causes: It may smell if the element is dirty or gets moldy. Due to the dirty element, vaporization amount is decreased and cooling efficiency will decline.



## Air filter(50816-201018)

Symptom: Poor wind, low cooling efficiency, and/or fan trouble  
Causes: If air filter is choked with dirt, cooling efficiency will decline. It may cause trouble in fan motor because of overload as well.

**Shizuoka Seiki Co.,Ltd.**

1300 Moroi, Fukuroi-shi, Shizuoka-ken 437-1121 JAPAN  
Phone: +81-538-23-3990 Fax: +81-538-23-3192  
E-mail: international@shizuokaseiki.jp